



## **Goshen – Tyler Lake Heights System 2022 Lead Compliance Testing Results**

**System is in Compliance**

**90<sup>th</sup> Percentile Lead Concentration (ppb)\* = 1**

<b>Rank</b>	<b>Collection Date</b>	<b>Lead Results (ppb)</b>
1	10-14-2022	None Detected
2	10-14-2022	None Detected
3	10-14-2022	None Detected
4	10-14-2022	None Detected
5	10-14-2022	None Detected
6	10-14-2022	None Detected
7	10-14-2022	None Detected
8	10-14-2022	None Detected
9	10-14-2022	None Detected
10	10-14-2022	None Detected
11	10-14-2022	None Detected
12	10-14-2022	1
13	10-14-2022	1
14	10-18-2022	1

**PWS ID#: CT0550011**

**\*ppb = parts per billion**

**For additional information on compliance determinations, please refer to the PDF entitled “CT Lead Compliance Testing Results – 90<sup>th</sup> Percentile” on the CT Lead Compliance Reports webpage.**