



**Goshen – Tyler Lake Heights System  
2021 Lead Compliance Testing Results  
System is in Compliance**

**90<sup>th</sup> Percentile Lead Concentration (ppb)\* = Not Detected**

| <b>Rank</b> | <b>Collection Date</b> | <b>Lead Results (ppb)</b> |
|-------------|------------------------|---------------------------|
| 1           | 04/05/21               | None Detected             |
| 2           | 04/05/21               | None Detected             |
| 3           | 04/05/21               | None Detected             |
| 4           | 04/05/21               | None Detected             |
| 5           | 04/05/21               | None Detected             |
| 6           | 04/05/21               | None Detected             |
| 7           | 04/05/21               | None Detected             |
| 8           | 04/09/21               | None Detected             |
| 9           | 05/03/21               | None Detected             |
| 10          | 05/03/21               | None Detected             |
| 11          | 05/03/21               | None Detected             |
| 12          | 04/05/21               | 1                         |

**PWS ID#: CT0550011**

**\*For additional information, please refer to the \*.pdf entitled: “CT Lead Compliance Testing Results – 90<sup>th</sup> Percentile Lead Concentration.”**