

## Seymour, Oxford and Beacon Falls - Valley System 2017 Lead Compliance Testing Results

## **System is in Compliance**

90<sup>th</sup> Percentile Lead Concentration (ppb)\* = 4

	Collection	Lead Results
Rank	Date	(ppb)
1	08/17/17	None Detected
2	08/17/17	None Detected
3	08/17/17	None Detected
4	08/17/17	None Detected
5	08/17/17	None Detected
6	08/17/17	None Detected
7	08/17/17	None Detected
8	08/17/17	None Detected
9	08/17/17	None Detected
10	08/17/17	None Detected
11	08/17/17	None Detected
12	08/17/17	None Detected
13	08/17/17	None Detected
14	08/17/17	None Detected
15	08/17/17	None Detected
16	08/17/17	None Detected
17	08/17/17	None Detected
18	08/17/17	None Detected
19	08/17/17	None Detected
20	09/14/17	None Detected
21	08/17/17	1
22	08/17/17	2
23	08/17/17	2
24	08/17/17	2
25	08/17/17	3
26	08/17/17	3
27	08/17/17	4
28	09/01/17	5



Stewards of the Environment™

29	08/17/17	2
30	08/17/17	2

PWS ID#: CT1240011

<sup>\*</sup>For additional information, please refer to the \*.pdf entitled: "CT Lead Compliance Testing Results – 90<sup>th</sup> Percentile Lead Concentration."