

**Aquarion Water Company
PFAS Sampling Results**

Town/City: Stamford

Water System Name	Sample Location	Test Date	All Results Reported as parts per trillion (ppt)					TOTAL PFAS (5)	Current CT DPH Guideline	Other PFAS Tested PFBS
			PFOA	PFOS	PFHpA	PFHxS	PFNA			
Stamford	Stamford Reservoirs, POE	Jun. 2019	4	ND	2	ND	ND	6	70	ND
	Stamford Reservoirs, POE	Jun. 2021	3	ND	ND	ND	ND	3	70	ND
	Woodway Road, Distribution Point	Aug. 2019	4	ND	ND	ND	ND	4	70	ND
	Wire Mill Well, POE - NOT IN SERVICE	-	-	-	-	-	-	-	70	-

Definitions:

ND - Not Detected

POE - point of entry. Sample collected after treatment as water enters the distribution system, before the first customer.